


ASSEMBLY INSTRUCTION SPINDLE BEDFRAME 5FT


PARTS LIST

No	DRAWING	DESCRIPTION	QTY
1		HEAD BOARD	1
2		FOOT BOARD	1
3		SIDE RAILS	2
4		SLATS	10
5		SLATS	4
6		SUPPORT BARS	1
7		SUPPORT LEGS	2


STEP 1



STEP 2



HARDWARE LIST

No	DRAWING	DESCRIPTION	QTY
A		BOLT	8
B		WASHER (Ø8x16)	8
C		LOCK WASHER (Ø8)	8
D		HEXAGON NUT	8
E		BOLT	2
F		SPANNER	1
G		ALEN KEY	1
H		CREW	32

ASSEMBLY INSTRUCTION SPINDLE BEDFRAME 5FT


PARTS LIST

NO	DRAWING	DESCRIPTION	QTY
1		HEAD BOARD	1
2		FOOT BOARD	1
3		SIDE RAILS	2
4		SLATS	10
5		SLATS	4
6		SUPPORT BARS	1
7		SUPPORT LEGS	2


HARDWARE LIST

NO	DRAWING	DESCRIPTION	QTY
A		BOLT	8
B		WASHER (Ø8x16)	8
C		LOCK WASHER (Ø8)	8
D		HEXAGON NUT	8
E		BOLT	2
F		SPANNER	1
G		ALEN KEY	1
H		CREW	32


STEP 3



STEP 4



STEP 5



FINISH

